

ESTIMATE TO REPAIR

VEHICLE NO. : SJP 9384 E
MAKE : MERCEDES BENZ
MODEL : E200 NGT
YEAR : 2009
CHASSIS NO : WDB2110412B431352

SURVEYOR NAME : *LKK*
DATE OF SURVEY : *01/01/2022*
TIME OF SURVEY : *10:00 AM*

DATE : 03-Jan-22
DATE OF ACCIDENT : 31-Dec-21
THIRD PARTY REF : SMG 330 G
THIRD PARTY REF : AIG ASIA PACIFIC INSURANCE PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	front bumper			\$ 1,300.00	X
2 pcs	front bumper chrome moulding		\$ 95.00	\$ 190.00	X
1 pc	front bumper retainer			\$ 68.00	X
1 pc	o/s front rim <i>850</i>		<i>Not for</i>	\$ 1,200.00	✓
1 pc	o/s front shock absorber			\$ 607.00	X
1 pc	o/s front knuckle arm			\$ 1,107.00	X
1 pc	o/s front knuckle bearing			\$ 645.00	X
1 pc	o/s front lower arm			\$ 689.00	X
1 pc	o/s front caster arm			\$ 437.00	X
	Less 10%				\$ 6,243.00
					\$ 624.30
					\$ 5,618.70
	To putty & Spray Paint				\$ 500.00
	To check front wiring & focus head lights				\$ 30.00
	To check wheel alignment				\$ 80.00
	To replace front under-carriage			\$ 200.00	X
	Labour charges				\$ 400.00
TG/VL	TOTAL				\$ 6,828.70

*Not to be used
1/1/2022
After Pain
4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-08 Sin Ming Autocare Singapore 575721
Tel: 65-64620893 Fax: 65-64689127 Email: sdmund@lmtm.sg
Co. Reg No. 199307277D Date: GST Reg No. M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd

\$103.00

*400l
15l
60l
X
250l*