



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KOH JANICE			Ref: CS/ASM22000094/Kty3e2 Date: 03/03/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJQ 6382A	Veh. Inspected	SNA 3922Z	
Policy No.	GA563784	Coverage (\$)	0.00	
Claim No.	S2M03Q0Q	Excess (\$)	0.00	
Assign From	KOH JANICE	Assign Date	04/01/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	SUZUKI SWIFT (M)	c.c	1586	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JSAEZC31S00204068	Colour	WHITE	
Odometer	155058 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/40 R17	GOODYEAR	7 mm	
L/H Front Tyre	215/40 R17	GOODYEAR	7 mm	
R/H Rear Tyre	215/40 R17	GOODYEAR	7 mm	
L/H Rear Tyre	215/40 R17	GOODYEAR	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S AND FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	01/01/2022	Inspection Date	04/01/2022	
Survey held at	RC AUTO 160 SIN MING DRIVE #06-20 SIN MING AUTOCITY SINGAPORE 575722			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>9 Working Days</b>	