

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1084/2021/JT
DATE : 3-Jan-22
WIP : 61742

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 4/1/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR AKKIHBBAL LAKSHMINARAYANA
SATYA PRAKASH
ADDRESS : BLK 202 CLEMENTI ROAD
#15-206
SINGAPORE 129783
TELEPHONE : HP +65 92959476
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070116674-01
VEHICLE NO : **SMU 5348 A**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 17/8/2020
ENGINE NO : CHZ C34240
CHASSIS NO : WAUZZZ8V3LA000409
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Dec-22
PLACE OF ACCIDENT : BLK 451 CLEMENTI AVE 3
CAR PARK

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 5348 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N \$ 280.00 ✓	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING AND RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00 500	✓
3	TO RESPRAY REAR BUMPER, REAR END PANELLING AND RHS REAR FENDER.	\$ 2,800.00 550	✓
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 5,372.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 5348 A

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 1,944.00	de ✓ 1555.20
2	REAR BUMPER FIXING PARTS	1	\$ 193.00	X nn
3	REAR BUMPER ADAPTER - RH	1	\$ 38.00	? X nn
4	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ LHX 32.00	RH? X nn
5	REAR BUMPER LOCKING MECHANISM - LH / RH	2	\$ LHX 59.00	RH? X nn
6	REAR BUMPER SPOILER	1	\$ 237.00	amb ✓ 189.60
7	REAR LIGHT REFLECTOR - RH	1	\$ 41.00	? X nn
8	REAR BUMPER REINFORCEMENT BEAM	1	\$ 603.00	? X nn
9	REAR BUMPER BRACKET - LH / RH	2	\$ LHX 56.00	RH? X nn
10	REAR BUMPER GUIDE SECTION OUTER - RH	1	\$ 66.00	? nn
11	REAR PARKING AID SENSOR - INNER / OUTER	2	TBC	X nn
12	REAR PARKING AID SENSOR SEAL RING	4	\$ 9.00	de ✓ x nn
13	REAR FENDER VENT TRIM - RH	1	\$ 68.00	? x nn
14	SUNDRIES		\$ 300.00	? X nn
TOTAL SPARE PARTS		:	\$ 3,646.00	
TOTAL LABOUR CHARGES		:	\$ 5,372.00	
GRAND TOTAL		:	\$ 9,018.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

Tanpin 97495749

Not Authorise Repair

Ex: to be advise

o 3 days

4/1/22 @ 240 pm,

Resurvey before paint

Tanpin @ Khandu.com.

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT