




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: PAY DANIEL			Ref: CS3/ASM22000112/Vvy3e2 Date: 25/01/2022 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 4443M	Veh. Inspected	SNA 9069Y
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S1M03PRM	Excess (\$)	0.00
	Assign From	PAY DANIEL	Assign Date	04/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 750LI	c.c	4395
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	WBAKB82040CY56203	Colour	BLACK
	Odometer	60722 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/35ZRF20	DUNLOP	5 mm
	L/H Front Tyre	235/35ZRF20	DUNLOP	5 mm
	R/H Rear Tyre	235/35ZRF20	DUNLOP	5 mm
	L/H Rear Tyre	235/35ZRF20	DUNLOP	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.			
5. General Information				
	Accident Date	30/12/2021	Inspect Date / Time	06/01/2022 ( 09:30 AM )
	Survey held at	14 AMK ST 63 BLK B		
	Repairer	ASSURE AUTO ASSIST PTE LTD		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$2,500			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	

Report Ref No. CS3/ASM22000112/Vvy3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.