



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDINGSINGAPORE 079120 ATTN: SALIHA SYED YUSOF			Ref: CS3/AIG21012259/Rvf3n2-1 Date: 08/02/2022 Code: AIG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKZ 2804S	Veh. Inspected	SMU 6699E	
Policy No.	1900004313	Coverage (\$)	0.00	
Claim No.	0657964204SG	Excess (\$)	0.00	
Assign From	SALIHA SYED YUSOF	Assign Date	05/01/2022	
2. Vehicle Particulars & Condition				
Make & Model	BMW 320I LED HL	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	WBA5F32050FJ00253	Colour	WHITE	
Odometer	23126 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R18	MICHELIN	6 mm	
L/H Front Tyre	225/45 R18	MICHELIN	6 mm	
R/H Rear Tyre	225/45 R18	MICHELIN	6 mm	
L/H Rear Tyre	225/45 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/11/2021	Inspection Date	03/12/2021	
Survey held at	14 ANG MO KIO ST 63 BLOCK B			
Repairer	ASSURE AUTO ASSIST PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	