



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22000123/Kqf3e2	
			Date: 07/02/2022	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SMB 1575L	Veh. Inspected	SJX 7965A
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/01/22/5066	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	05/01/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HYUNDAI I45 (A)	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	KMHEC41BMBA160099	Colour	METALLIC DARK BROWN
	Odometer	279355 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	215/55 R17	YOKOHAMA	3 mm
	L/H Front Tyre	215/55 R17	YOKOHAMA	3 mm
	R/H Rear Tyre	215/55 R17	WINDFORCE	7 mm
	L/H Rear Tyre	215/55 R17	WINDFORCE	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	03/01/2022	Inspection Date	05/01/2022
	Survey held at	S THREE AUTOMOTIVE & RECOVERY PTE LTD BLK 8 SIN MING IND EST #01-64/66 SINGAPORE 575643		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	