

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Tel : 6721-9016 Fax : 6844-5185

Reg : 201838521G

Vehicle Number : SLR9045A
Vehicle Model : OPEL ASTRA
Accident Date : 19/12/2021
Original Reg Date : 30/8/2017

Date : 21/12/2021
Chassis : W0LBE8EA7H8052201
TP Ins. : AIG

Xiao Tony

ESTIMATE

1	1	FRT BONNET	new		\$ 1,318.00	+
2	1	FRT BUMPER	new		\$ 1,495.00	+
3	1	FRT BUMPER SIDE RETAINER LH - GUIDE	new		\$ 136.00	+
4	1	FRT BUMPER SIDE RETAINER LH - UPP	new		\$ 106.00	+
5	1	FRT BUMPER BRACKET LH	new		\$ 192.00	+
6	1	FRT BUMPER BRACKET TOP CENTRE	new		\$ 198.00	+
7	1	FRT BUMPER SPONGE	new		\$ 254.00	+
8	1	FRT BUMPER PARKING SENSOR	new		\$ 272.00	+
9	1	FRT BUMPER PARKING SENSOR SEAL	new		\$ 12.00	+
10	1	FRT GRILLE ASSY	new		\$ 800.00	+
11	1	FRT GRILLE LOGO	new		\$ 160.00	+
12	1	DAYLIGHT CONTROL UNIT	new		\$ 664.00	+
13	1	LH HEADLAMP	new		\$ 879.00	+
14	1	LH FOG LAMP	new		\$ 325.00	+
15	1	LH FOG LAMP COVER	new		\$ 120.00	+
16	1	FRT FENDER LH	new		\$ 511.00	+

3401
3060.80
\$ 7,442.00
Less 10% \$ 744.20
\$ 6,697.80

Special Nett

1	1 pc	Frt Number Plate with Cover	new	\$ 65.00	+
2	10 pc	Frt Bumper Clip	new	\$ 50.00	30
3	10 pc	Frt Fender Inner Shield Clip	new	\$ 60.00	+
4	10 pc	Frt Grille clip	new	\$ 60.00	+
5	1 pc	Body Panel Joint Sealer	new	\$ 120.00	+

1 pc Frt Bumper body kit cut

\$ 350

380

Labour charge

To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 1,000.00	300
Carry out spray painting on affected area	\$ 1,000.00	400

To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair			\$	120.00	30
To conduct anti rust of tuff coat			\$	100.00	+
To refocus headlamp			\$	100.00	+
To reset faulty code			\$	300.00	+ 150
To remove and refix front sensor and conduct test			\$	80.00	50

830

Total \$ 9,752.80

GST 7% \$ 682.70

Grand Total \$ 10,435.50

Adrian Lij
w/s 03/01/22

03 Day.

total: 4370.90
f/s: 3.5K, ✓

3.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: