

## TRANS EUROKARS PTE LTD

27A TANJONG PENJURU, SINGAPORE 609042



## **ESTIMATE COST OF REPAIRS**

INDIA INTERNATIONAL INSURANCE P/L NAME: WIP: 44986 64 CECIL STREET ADDRESS : **EXCESS:** #04-#05 IOB BUILDING DATE: 5-Jan-22 SINGAPORE 049711 ATTN.: MOTOR CLAIMS TEL: FAX: VEH NO: SMW6973C DATE IN: **CONTACT PERSON:** JESS MILEAGE: THIRD PARTY CLAIM **CHASSIS NO:** JM6GL1073L0405846 **TYPE OF CLAIM:** DATE REG. MODEL: 1-Dec-20 POLICY NO. : MAZDA 6 **NATURE OF WORKS DESCRIPTION QTY** UNIT PRICE DISC % PARTS NO **REVISED** PRICES NO 1st Supp REAR BUMPER 1 1 1,154.80 MGSK2-50-221ABB 1,154.80 TAPE, PROTECTOR 4 4.70 MBCKA-50-EM1 18.80 RETAINER S.S ULTRASONIC CENTER 2 3 18.20 MKD45-67-UC5A13 36.40 SENSOR ULTRASONIC CENTER 2 181.70 -MGMK6-67-UC1 13 363.40 5 BRACKET CENTER REAR BUMPER 1 5.40 MDFR5-50-251 5.40 6 REINFORCEMENT REAR 1 538.30 MGHK1-50-260 538.30 TAPE SEAL 2 13.70 27.40 7 MGSH7-50-2G1 COVER TOWING RH REAR 1 46.60 MGSH7-50-EK1 BB 46.60 REFLECTOR RH 41.20 41.20 MGRF5-51-5L0A 9 1 RIVET 2 9.20 MTK21-50-355 18.40 10 11 FASTENER 6 8.00 MEA01-50-037 48.00 GASKET TAIL LAMP RH 46.00 12 1 46.00 MGRF5-51-153 GASKET TAIL LAMP LH 46.00 46.00 13 1 MGRF5-51-163 **SUPPLEMENTARY DESCRIPTION** UNIT PRICE DISC % 1st Supp NO QTY PARTS NO **REVISED** PRICES 1 **TOTAL PARTS** 2,390.70 **TOTAL PARTS COST** 2,390.70 **Labour Description REVISED PRICES** TO REPLACE REAR BUMPER AND REPAIR ALL AREAS AFFECTED BY THE ACCIDENTS. 1,320.00 1 TO RESPRAY REAR BUMPER AND ALL AREAS AFFECTED BY THE ACCIDENTS. 2 1,260.00 MZ-BR-REVSEN TO TRANSFER REVERSE SENSORS. 660.00 MZ-BR-ELECTR TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. 250.00 MZ-BR-REPROGTO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS. 300.00

6	MZ-BR-SUNDRI SUNDRIES.			50.00	
SUPPLEMENTARY LABOUR DESCRIPTION					
		REVISED	PRICES		
1		#N/A			
REMARKS:  IT IT IS UNLY AN ESTIMATE FROM VISUAL INSPECTION  AND SHOULD THERE BE MORE DAMAGES FOUND DURING  THE PROCESS OF REPAIRING, YOU WILL BE INFORMED  TOTAL			-	3,840.00	
			-	2,390.70	
			-	6,230.70	
BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE  LESS EXCESS			-	-	
NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE TOTAL AFTER EXCESS			-		
APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN  GST 7%			-	-	
	SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES GRAND TOTAL		-	-	

TR	ANS EUROKARS PTE LTD
Λt	horised Signature