

1 of 2 ?

100%

Find | Next



LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSG INSURANCE (S) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807		Ref: CS/MSG22000142/Utf3 Date: 05/01/2022 Code: MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SME 3034C	Veh. Inspected	SMX 1041U
Policy No.	29149830MCY	Coverage (\$)	0.00
Claim No.	639601	Excess (\$)	0.00
Assign From	MERIMEN (NOR AZIAN BINTE NOORDIN)	Assign Date	05/01/2022
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	Colour		
Odometer	-	Steering	
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	29/11/2021	Inspection Date	05/01/2022
Survey held at	BLK 15 KAKI BUKIT ROAD 4, #01-53		
Repairer	ZOOM AUTOWERKS PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			