

E M SOLUTION PTE LTD

160 Sin Ming Drive #03-18/19, Sin Ming Autocity

Singapore 575722

Tel: 64560226 Fax: 64584500

GST Reg. No: 201016308K

ESTIMATE

Date: 14th January 2022

Mr **Lim Wei Qiang**
Blk 739 Jurong West St 73, #06-58
Singapore 640739

Veh No: **SLN 5055T**
Make/Model: **Chev Orlando**
Chassis No: **KL1YA7589HK610757**
Date of Acc: **31.12.2021**
TP Veh No: **SHB 6388L**

S/No	Qty	Description	Unit Price	Amount
Materials				
1	1 pc	Rear Door LH <i>st</i>		\$ 2,200.00 <i>1841</i>
2	1 pc	Rear Door Inner Trim Board LH <i>Xan</i>		\$ 580.00 <i>X</i>
3	1 pc	Rear Door Weatherstrip LH <i>an</i>		\$ 65.00 <i>/</i>
4	1 pc	Rear Fender LH <i>repair</i>		\$ 880.00 <i>X</i>
5	1 pc	Rear Wheel Arch Garnish LH <i>scu</i>		\$ 180.00 <i>/</i>
6	1 pc	Side Skirt LH <i>Xan</i>		\$ 480.00 <i>X</i>
7	1 pc	Rear Fender Liner LH <i>Xan</i>		\$ 150.00 <i>X</i> <i>2086</i>
			<i>1877.40</i>	\$ 4,535.00 <i>10%</i>
			<i>30.00</i>	\$ 453.50
			<i>1300.00</i>	\$ 4,081.50 <i>1877.40</i>
Special Nett				
8	1 set	Wheel Arch Garnish Clips <i>an</i>		\$ 45.00 <i>30</i>
9	1 set	Fender Liner Clips <i>Xan</i>		\$ 45.00 <i>X</i>
10	1 pc	Quarter Glass Sealant <i>Xan</i>		\$ 40.00 <i>X</i> <i>30</i>
11	1 pc	Rear Sport Rim <i>repair</i>		\$ 450.00 <i>X</i>
			<i>3207.40</i>	
			<i>20%</i>	
			<i>2565.92</i>	
			Parts Total	\$ 4,661.50
Labour				
1		To remove & rearrange electrical wirings, check lightings		\$ 80.00 <i>40</i>
2		To remove, transfer rear door components.		\$ 100.00 <i>60</i>
3		To remove & instal fender quarter glass		\$ 100.00 <i>Xan</i>
4		To remove, instal cushion seat, trim garnishes to facilitate repairs		\$ 200.00 <i>60</i>
5		To remove, repair & replace damaged bodyparts and where consistent to the accident.		\$ 1,200.00 <i>500</i>
6		Putty and respray painting on affected portions.		\$ 1,000.00 <i>600</i>
7		Rust proofing on affected portions.		\$ 100.00 <i>40</i>
			<i>415 - \$2,550</i>	
			Labour Total	\$ 2,780.00
			Total Parts & Labour	\$ 7,441.50

for E M Solution Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Up 500000 68
4 days
4/5
18/01/22 P1150
Reg after repair