



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref: CS/CTI22000182/Aqy3	
3 ANSON ROAD #16-00			Date: 06/01/2022	
SPRINGLEAF TOWERSINGAPORE 079909			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKC 5561T	Veh. Inspected	SKN 52X	
Policy No.	DMPCSNW00165072100	Coverage (\$)	0.00	
Claim No.	SNM22D200098/C02/TOHHS	Excess (\$)	0.00	
Assign From	ALFRED TOH	Assign Date	06/01/2022	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	26/12/2021	Inspection Date	06/01/2022	
Survey held at	SR AUTOWORKS PTE LTD 8 KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				