

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	FRONT BUMPER CLIPS <i>men</i>	1	\$ 50.00	\$ 50.00 ✓
2	SUPPORT PANEL SEALANT <i>2</i>	1	\$ 80.00	\$ 80.00 +
3	RADIATOR COOLANT <i>men</i>	1	\$ 80.00	\$ 80.00 +
4	FRONT GRILLE CLIP	1	\$ 40.00	\$ 40.00 +
5	FRONT FENDER SEALANT LH	1	\$ 80.00	\$ 80.00 +
6	FRONT FENDER INNER COWLING CLIPS <i>2 men</i>	1	\$ 60.00	\$ 60.00 +
7	WINDSCREEN SIDE MOULDING CLIPS	1	\$ 50.00	\$ 50.00 +
8	FRONT TYRE LH <i>2 men</i>	1	\$ 380.00	\$ 380.00 +
9	FRONT SPORT RIM LH <i>30</i>	1	\$ 1,200.00	\$ 1,200.00 +
SPECIAL NETT				\$ 2,020.00

LABOUR	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00 <i>800</i>
TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00 <i>800</i>
TUFF COAT	\$ 250.00 <i>30</i>
WIRING AND BULB CHECK	\$ 50.00 <i>30</i>
REMOVE AND REFIX AIRCON CONDENSOR AND REFILL GAS	\$ 200.00 +
REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 200.00 +
REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 600.00 +
CONDUCT WHEEL ALIGNMENT <i>1060</i>	\$ 120.00 +
LABOUR TOTAL	\$ 4,620.00

Total Parts Cost	\$ 12,991.00
Total Labour Cost	\$ 4,620.00
Total Repair Cost	\$ 17,611.00

APPROVED DETAILS
 NO. OF WORKING DAYS
 PART BY PART OR LUMP SUM
 DATE & TIME OF SURVEY
 SURVEYED BY
 CONTACT NUMBER
 FAX NUMBER

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Adnan Lj
r/s 06/01/22
04 Days

total: 3360.15
r/s: 2.712 ✓

310