

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN	ISURANCE (S) PTE LTD	ı	Ref:	CS/CTI22000184/R1qy3	
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909	1	Date:	06/01/2022	
			(	Code:	СТІ	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	PC 821S	Veh. Inspected		SLP 4767T	
	Policy No.	DMB1SNW00017502100	Coverage (\$)		0.00	
	Claim No.	SNM22D200106/C02/IRENE	Excess (\$)		0.00	
	Assign From	IRENE TAY	Assign Date		06/01/2022	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	04/01/2022	Inspection Date	•	06/01/2022	
	Survey held at	BORNEO MOTORS (S) PTE LTI	)			
		2 PANDAN CRESCENT SINGAPORE 128462				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					