



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICCI1		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No. 0				
			Document Date 14/01/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	NSP151R	CEXRKT Q1	07/06/2017	SLP4767T	0	12463	75/DS/SLP4767T
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFB29F3902011936		2NRX159042	60	Ng Mei Yen	06/01/2022	8.00	12/01/2022 18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:PC821S ACC DATE:04/01/2022 DRIVE IN:04/01/2022 DATE-IN: DATE SURVEY:06/01/22 NO OF REPAIR DAYS:5 DAYS BY:RASUL LKK				30.00	
2	B	BP-LAB2 CHECK WIRING & CONDUCT LEAK TEST	BP60			180.00	
3	B	BP-LAB2 RESET ECU UPON COMPLETION OF REPAIR	BP60			180.00	
4	L	BP-LPO SUPPLY REGN PLATE (PO#33853)	0263			80.00	
5	B	BP-LAB2 REPL ACC AFF AREA STRAIGHTEN & PANEL BEAT ACC AFF AREA	BP60			1440.00	
6	B	BP-RES2 RESPRAY ACC AFF AREA	*			2360.00	
7	1	K52119-0U920 COVER, FR BUMPER, L	1.00	525.80		525.80	
8	2	K53112-0D300 GRILLE, RADIATOR, LW	1.00	304.10		304.10	
9	3	K52127-0D430 COVER, FR BUMPER HOL	1.00	63.40		63.40	
10	4	K53101-0D904 GRILLE SUB-ASSY, RAD	1.00	216.60		216.60	
11	5	K53121-0D200 MOULDING, RADIATOR G	1.00	73.40		73.40	
12	6	K53124-0D140 MOULDING, RADIATOR G	1.00	73.40		73.40	
13	7	K53301-0D160 HOOD SUB-ASSY	1.00	982.10		982.10	
14	8	K81110-0D831 HEADLAMP ASSY, RH	1.00	644.20		644.20	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy



Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462. Tel no.: 6631 1188



ESTIMATE

Account Details				Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept				S1000003 / ICCI1		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925			
				Document No. 0					
				Document Date 14/01/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2017	NSP151R	CEXRKT Q1	07/06/2017	SLP4767T	0	12463	75/DS/SLP4767T		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
MHFB29F3902011936		2NRX159042	60	Ng Mei Yen	06/01/2022	8.00	12/01/2022	18.00	
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
15	9	K81150-0D831 HEADLAMP ASSY, LH				1.00	644.20		644.20
16	0	K90975-T2008 EMBLEM, SYMBOL				1.00	61.90		61.90
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 7,859.10		
					Parts	3,589.10	GST 7.00%		550.14
					Labour	4,190.00	Less		0.00
					Sublet	80.00			
					Lubrication/Fluid	0.00			
					Others	0.00	Amount Due		8,409.24

Customer Copy