

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 03 Jan 2022)

Parts: 143 **HYUNDAI I40 1.7 D CRDi (A) (Catalogue Merimen Singapore 1.0)**

Labour: Repairer's **(Price-denominated Standard List)**

Print Code: ComfortDelGro Engineering Pte Ltd/SHC8506U/03/01/2022 16:51

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER	20.00	0.00	cut / 553.00 FL
2	1		*REAR BUMPER CLIPS	20.00	0.00	n/c / 22.00 FL
3	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	cut / 428.40 FL
4	1		*REAR BUMPER UNDER COVER	20.00	0.00	scr / 228.00 FL
5	1		*REAR BUMPER REVERSE SENSOR	0.00	0.00	cut / 135.70 F
Sub Total (S\$)						1,367.10
- List Item Discount on L Items (S\$)						246.28
Total Parts (S\$)						1,120.82

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHC8506U/03/01/2022 16:51. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

[illegible]

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11 09

Sub Total (\$\$)

44. 503

No Particulars

Lab. Type

Amount

Labour Items

1 PANEL BEATING

None

24 210
450 70

2 SPRAY PAINTING CHARGE

Nestlé

2. 50000000

REMOVE/REFIX REVERSE SENSOR

Now

7050 50

Gross Labour Cost (\$\$)

510.00

ComfortDelGro Engineering Pte Ltd/SHC8506U/03/01/2022 16:51 Not valid without Reference section
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thuan Chhay to Lou

82235769

4/1/22 1100

LIS ✓ after repair photo
2 delays up ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

F: \$1050

repair days 2