



DICKSON GROUP
Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

2-8499

QUOTATION

L-3240

QUOTATION FOR

NAME: LONPAC INSURANCE BHD
COMPANY NAME: LONPAC INSURANCE BHD
STREET ADDRESS: 300 Beach Road, #17-04/07 The Concourse
POSTAL CODE: Singapore 199555
PHONE: 6250 7388

Not Authorized
U/S
Telephoto After
10 days?
MP. 90996608
tel. 62503581
7/1/22

DATE: 6/1/2022
REF: SKH2996R
VEHICLE NO.: SKH2996R
MAKE: MAZDA
MODEL: 3
PREPARED BY: POON

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
	LABOUR						
1	TO REMOVE & REFIX REAR DASHBOARD, INNER TRIM COVER AND CLEAN UP ALL BROKEN GLASSES	1		\$ 200.00	\$ 200.00	80	\$ 200.00
2	TO REMOVE & REFIX ELECTRICAL WIRING, TAIL LAMPS AND TEST FOR PROPER FUNCTIONING	1		\$ 120.00	\$ 120.00	30	\$ 120.00
3	TO REMOVE & REFIX REVERSE SENSORS	1		\$ 120.00	\$ 120.00	50	\$ 120.00
4	TO REMOVE & REFIX RR WINDSCREEN	1		\$ 200.00	\$ 200.00	120	\$ 200.00
5	TO REMOVE & REFIX EXHAUST PIPE TO ASSIST FOR REPAIR	1		\$ 1,200.00	\$ 1,200.00	11X	\$ 1,200.00
6	TO DO ELECTRICAL 4 WHEEL ALIGNMENT	1		\$ 120.00	\$ 120.00	11X	\$ 120.00
7	TO REMOVE & REFIX FUEL TANK TO ASSIST FOR REPAIR	1		\$ 280.00	\$ 280.00	60	\$ 280.00
8	TO REMOVE & REFIX REAR LH & RH SUSPENSION TO ASSIST FOR REPAIR	1		\$ 400.00	\$ 400.00	11X	\$ 400.00
9	TO PROVIDE SKILL LABOUR TO REMOVE ALL REAR DAMAGED PANELS, PANEL BEAT, CUT AND WELD IN PLACE NEW PARTS AND PANELS WITH FULL REALIGNMENT TO PROVIDE SKILL LABOUR AND MATERIAL TO PREPARE AND PAINT ALL NEW PARTS AND PANELS	1		\$ 2,000.00	\$ 2,000.00	1600	\$ 2,000.00
10	TO PROVIDE SKILL LABOUR TO REMOVE ALL REAR DAMAGED PANELS, PANEL BEAT, CUT AND WELD IN PLACE NEW PARTS AND PANELS WITH FULL REALIGNMENT TO PROVIDE SKILL LABOUR AND MATERIAL TO PREPARE AND PAINT ALL NEW PARTS AND PANELS	1		\$ 2,000.00	\$ 2,000.00	1300	\$ 2,000.00
	PARTS						
1	REAR NO PLATE WITH CASING	1		\$ 45.00	\$ 45.00	Self	\$ 45.00
2	REAR BUMPER	1	1096	\$ 1,444.00	\$ 1,444.00	Dis	\$ 1,444.00
3	REAR BUMPER CLIPS	10		\$ 5.00	\$ 50.00	net	\$ 50.00
4	REAR BUMPER SIDE RETAINER LH & RH	2		\$ 39.00	\$ 78.00	Self	\$ 78.00
5	REAR BUMPER SIDE BRACKET LH & RH	2		\$ 14.00	\$ 28.00	Self	\$ 28.00
6	REAR BUMPER REFLECTOR LH & RH	2		\$ 63.00	\$ 126.00	Self	\$ 126.00
7	REAR BUMPER REINFORCEMENT	1	507	\$ 557.00	\$ 557.00	Self	\$ 557.00
8	REAR BUMPER REVERSE SENSOR 1 SET	1		\$ 400.00	\$ 400.00	Should	\$ 400.00
9	REAR NO PLATE LAMP LH & RH	1		\$ 164.00	\$ 164.00	Self	\$ 164.00
10	REAR TRUNK	1	1067	\$ 1,220.00	\$ 1,220.00	DD	\$ 1,220.00
11	REAR TRUNK HINGES LH & RH	2		\$ 129.00	\$ 258.00	Self	\$ 258.00
12	REAR TRUNK REFLECTOR LH & RH	2		\$ 494.00	\$ 988.00	CR	\$ 988.00
13	REAR TRUNK THIRD BRAKE LAMP	1	350	\$ 515.00	\$ 515.00	CR	\$ 515.00

s/w
40
—
—
—
—
X
—
200 sp.
X
—
—
—
—

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
14	REAR TRUNK MAZDA 3 LOGO	1		\$ 39.00	\$ 39.00	ner	\$ 39.00
15	REAR TRUNK MAZDA LOGO	1		\$ 75.00	\$ 75.00	ner	\$ 75.00
16	REAR TRUNK DAMPER LH & RH	2		\$ 82.00	\$ 164.00	17	\$ 164.00
17	REAR TRUNK INNER TRIM COVER	1		\$ 160.00	\$ 160.00	SVC	\$ 160.00
18	REAR TRUNK INNER TRIM COVER CLIPS	10		\$ 5.00	\$ 50.00	17	\$ 50.00
19	REAR TRUNK INNER LOCK	1		\$ 177.00	\$ 177.00	ner/bm	\$ 177.00
20	REAR TRUNK INNER LOCK HATCH	1		\$ 35.00	\$ 35.00	17	\$ 35.00
21	REAR TRUNK INNER RUBBER	1		\$ 98.00	\$ 98.00	ner	\$ 98.00
22	TAIL LAMP LH & RH	2		\$ 494.00	\$ 988.00	one	\$ 988.00
23	REAR FENDER LH & RH	2	O/S R	\$ 1,129.00	\$ 2,258.00	mls/buc	\$ 2,258.00
24	REAR FENDER INNER TRIM COVER	1		\$ 204.00	\$ 204.00	SVC	\$ 204.00
25	REAR FENDER INNER TRIM COVER CLIPS	10		\$ 5.00	\$ 50.00	17	\$ 50.00
26	REAR END PANEL	1		\$ 422.00	\$ 422.00	Svc/17	\$ 422.00
27	REAR END PANEL TOP GARNISH	1		\$ 204.00	\$ 204.00	Dis	\$ 204.00
28	REAR END PANEL TOP GARNISH CLIPS	10		\$ 5.00	\$ 50.00	17	\$ 50.00
29	SPARE TRYE HOUSING PANEL	1		\$ 1,070.00	\$ 1,070.00	R	\$ 1,070.00
30	SPARE TRYE HOUSING BOARD	1		\$ 513.00	\$ 513.00	SVC	\$ 513.00
31	REAR WINDSCREEN	1		\$ 945.00	\$ 945.00	shattered	\$ 945.00
32	SEALANT	1		\$ 45.00	\$ 45.00	ner	\$ 45.00
33	REAR DASHBOARD	1		\$ 437.00	\$ 437.00	SVC	\$ 437.00
34	REAR FENDER INNER SHIELD LH & RH	2		\$ 62.00	\$ 124.00	SVC	\$ 124.00
35	REAR FENDER INNER SHIELD CLIPS	12		\$ 5.00	\$ 60.00	17	\$ 60.00
36	REAR EXHAUST PIPE	1		\$ 1,077.00	\$ 1,077.00	17	\$ 1,077.00
37	REAR EXHAUST PIPE END COVER	1		\$ 55.00	\$ 55.00	ner	\$ 55.00
38	REAR FENDER INNER PANEL LH & RH	2		\$ 978.00	\$ 1,956.00	R	\$ 1,956.00

REMARKS:

(202)

SUBTOTAL	\$ 23,769.00	SUBTOTAL	\$ 23,769.00
GST 7%	\$ 1,663.83	GST 7%	1663.83
TOTAL	\$ 25,432.83	TOTAL	\$ 25,432.83

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

(CUSTOMER'S SIGNATURE AND COMPANY STAMP)

(AUTHORISED SIGNATURE)

