

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1085/2021/JT
DATE : 4-Jan-22
WIP : 61204

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/1/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TAN PECK HWEE
ADDRESS : 7 JURONG LAKE LINK
#03-25
SINGAPORE 648163
TELEPHONE : HP +65 90711701
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900255667-01
VEHICLE NO : **SMR 1701 E**
MODEL CODE : AUDI A1 SB ADVANCED 1.0
MODEL YEAR : 29/11/2019
ENGINE NO : DKJ 046332
CHASSIS NO : WAUZZZGB9LR008362
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Dec-21
PLACE OF ACCIDENT : PLQ BUILDING CAR PARK



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 1701 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	X 250
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW LHS WING MIRROR ASSY.	S/N \$ 280.00	X.
4	TO DISMANTLE AN RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	1000 ✓
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND LHS WING MIRROR COVER.	\$ 2,500.00	1100 ✓
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	✓ ✓
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 6,062.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 1701 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>replaced</i> torn	1	\$ 1,634.00	✓ 1307.20
2	FRONT BUMPER FIXING PARTS <i>3 new</i>	1	\$ 137.00	+
3	FRONT BUMPER SPOILER - LH	1	\$ 100.00	+
4	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	1	\$ 211.00	+
5	FRONT BUMPER CLOSING ELEMENT	1	\$ 167.00	+
6	FRONT BUMPER GUIDE PROFILE - LH <i>new</i>	1	\$ 36.00	+
7	FRONT BUMPER GUIDE SECTION - LH	1	\$ 107.00	+
8	FRONT FENDER - LH <i>Dented</i>	1	\$ 978.00	✓ 782.40
9	FRONT FENDER BRACE - LH <i>nn</i>	1	\$ 54.00	? X
10	FRONT FENDER BRACKET - LH <i>nn</i>	1	\$ 37.00	? X
11	FRONT FENDER BRACKET CENTER - LH <i>nn</i>	1	\$ 14.00	? X
12	FRONT WHEEL HOUSING LINER <i>new</i> chipped	1	TBC	+
13	HEADLIGHT - LH <i>new</i>	1	\$ 4,288.00	+ 3430.40
14	LIFT CYLINDER - LH <i>new</i>	1	\$ 142.00	+
15	LIFT CYLINDER HOSE <i>new</i>	1	\$ 59.00	+
16	ALUMINIUM RIM - LH <i>col</i>	1	\$ 962.00	✓ 769.60
17	WING MIRROR MOUNTING - LH <i>new</i>	1	\$ 588.00	+
18	WING MIRROR CAP - LH <i>new</i>	1	\$ 130.00	+
19	SIGNAL INDICATOR - LH <i>new</i>	1	\$ 92.00	+
20	SUNDRIES <i>nn</i>		\$ 250.00	? X
TOTAL SPARE PARTS		:	\$ 9,986.00	
TOTAL LABOUR CHARGES		:	\$ 6,062.00	
GRAND TOTAL		:	\$ 16,048.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adnan King
06/01/22 J.

Not Authorized, 05 Days.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: