

Your Ref: RT/YJ/348/2021/ml

Date: 08th Mar 2022

Our Ref: CS1/LAW22000228/Tqf3e2

M/s Tan Chin Hoe & Co

24 Raffles Place

#24-01 Clifford Centre

Singapore 048621

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBE 2575U**INSURED VEHICLE: SKK 8679B****ACCIDENT DATE: 24/01/2021**

We thank you for your instruction on 07/01/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBE 2575U from M/s Prominent Appraiser Services Pte Ltd.
- b) Survey report by QuanTum Risk Management with colour photographs.
- c) Final Repair Bill of GBE 2575U from M/s Yi Heng Motor Workshop.
- d) Singapore Accident Statement of Vehicles GBE 2575U and SKK 8679B.
- e) Police Report of Vehicles SKK 8679B.
- f) Colour damaged vehicle photographs of GBE 2575U.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GBE 2575U
Make & Model	: Toyota Hiace Van 3.0 Auto
Chassis Number	: KDH2010176781
Year of Registration	: 2015
Engine Capacity	: 2982 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.