



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. BICYCLE

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SET 2021 GIANT DEFY ADVANCED PRO 2 DISC FRAME (CONSISTENT)	CRACKED	3,400.00	3,400.00
1	BARTAPE (HANDLE BAR TAPE) (CONSISTENT)	TORN	55.00	55.00
1	GIANT CONTACT SLR HANDLERBAR CARBON (CONSISTENT)	BENT	395.00	395.00
1	WHEEL TRUING (WHEEL) (CONSISTENT)	BENT	120.00	120.00
1	SADDLE GIANT FLEET SL (SEAT) (CONSISTENT)	CUT	135.00	135.00
1	AXLE LEVER (REAR) (CONSISTENT)	BENT	45.00	45.00
	LESS 10% DISCOUNT		-	-415.00
			4,150.00	3,735.00
GRAND TOTAL			4,150.00	3,735.00

RECOMMENDED COST OF REPAIRS			3,735.00
------------------------------------	--	--	-----------------

Report Ref No. CS/ASM22000241/Eny3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.