

YOUR REF. TP 220101
OUR REF. JUV608
TO. AXA INSURANCE
ATTN. MOTOR CLAIMS DEPARTMENT

CHASSIS NO.
ENGINE NO.
MAKE / MODEL.
YEAR OF MAKE.
ACCIDENT DATE.

BENELLI LEONCINO 250
2020

ESTIMATE FOR MOTORCYCLE NO. JUV608

S/N	DESCRIPTION	QTY	PRICE
1	HANDLE BAR	1	\$180.00 / BT
2	HANDLE BALANCER LH	1	\$95.00 / nec
3	HANDLE BALANCER RH	1	\$95.00 / nec
4	MIRROR LH	1	\$112.00 / scr
5	MIRROR RH	1	\$112.00 X Svc
6	CLUTCH LEVER	1	\$104.00 / DT S
7	CLUTCH LEVER HOLDER	1	\$86.00 / scr
8	CLUTCH LEVER BOLT	1	\$10.00 / BT
9	CLUTCH CABLE	1	\$55.00 X Svc
10	FRONT SIGNAL LIGHT LH	1	\$140.00 / scr
11	RADIATOR SIDE COVER LH	1	\$295.00 X Svc
12	FRONT MUDGUARD	1	\$210.00 X Svc
13	FORK ASSY LH	1	\$1,243.00 / Xr 80
14	FORK ASSY RH	1	\$1,243.00 / Xr 80
15	FORK UNDERBRACKET	1	\$659.00 / X Svc
16	STEERING CONE BEARING	1	\$110.00 / X Svc
17	STEERING CONE SEAL PIECE	1	\$27.00 / X Svc
18	GEAR PEDAL LEVER	1	\$142.00 / scr
19	GEAR PEDAL LEVER RUBBER	1	\$20.00 / cut
20	GEAR SHIFTER ROD ASSY	1	\$130.00 / BT
21	ENGINE CASE COVER LH	1	\$358.00 / Cra
22	ENGINE CASE COVER GASKET LH	1	\$48.00 / X Svc
23	SIDE STAND	1	\$95.00 / scr
24	FRONT FOOTREST RH	1	\$77.00 / scr
25	FRONT FOOTREST RUBBER RH	1	\$42.00 / nec
26	REAR FOOTREST LH	1	\$87.00 / scr
27	REAR FOOTREST RUBBER LH	1	\$25.00 / nec
28	REAR FOOTREST BRACKET LH	1	\$280.00 / scr
29	REAR FOOTREST RH	1	\$87.00 / mis
30	EXHAUST MUFFLER PROTECTOR FRONT	1	\$85.00 / one srt
31	EXHAUST MUFFLER PROTECTOR REAR	1	\$175.00 / DT / scr
32	EXHAUST PIPE SYSTEM	1	\$980.00
33	EXHAUST PIPE HEADER GASKET	1	\$30.00 / nec

TOTAL:	\$7,437.00
LESS 10%	-\$743.70
G.TOTAL	\$6,693.30

SPECIAL NETT

AFTERMARKET FRAME SLIDER LH
 AFTERMARKET FRAME SLIDER RH
 HEAVY DUTY REAR BOX RACK
 AFTERMARKET ALUMINUM BOX
 FULLY SYNTHETIC ENGINE OIL 10W40

\$160.00 / BT 80
 \$160.00 / BT 80
 \$180.00 / ~~BT~~ 80
 \$670.00 / ~~BT~~ 400
 \$30.00 KNW

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS
 TO CONDUCT FORK ALIGNMENT
 TO PERFORM ELECTRICAL CHECK
 RESPRAY CHASSIS RH

\$450.00 250
 \$120.00 140
 \$30.00 20
 \$200.00 70

TOTAL	\$8,693.30
7% GST	\$608.53
G.TOTAL	\$9,301.83

Thavan@lkkauto.com
 82235769
 7/1/22 1600
 L/S after repair photo
 5 days w/p

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

[Signature]
 3000