

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI22000257/Uvy3n2	
		TINSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	18/01/2022	
			Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SML 9920T	Veh. Inspected	SCN 9788S	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10013280/KY	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	10/01/2022	
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI ELANTRA (A)	c.c	1591	
	Engine No.	HIDDEN	Year of Reg.	2013	
	Chassis No.	KMHDH41CMDU674608	Colour	SILVER	
	Odometer	135211 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	CONTINENTAL	6 mm	
	L/H Front Tyre	205/55 R16	CONTINENTAL	6 mm	
	R/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm	
	L/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	_	General Information			
	Accident Date	06/01/2022	Inspection Date	10/01/2022	
	Survey held at	TAN LIM MOTOR PTE LTD			
		NO.1 DEFU LANE 6 SINGAPORE 539365			
5a.		Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: