

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	06 Jan 2022 19:35	Clm Veh Model Changed		[] Merimen Administrator
2	06 Jan 2022 19:35	Clm Created	Reg No: SKV995H. Policy No: 1900112959-01. Acct Date: 2022/01/05. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SP0R22160007	[I] Merimen Administrator
3	10 Jan 2022 10:30	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CELINE FONG
4	10 Jan 2022 10:30	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CELINE FONG
5	10 Jan 2022 10:30	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CELINE FONG
6	10 Jan 2022 10:30	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/01/19	[A] CELINE FONG
7	10 Jan 2022 10:30	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] CELINE FONG
8	10 Jan 2022 10:30	Clm Registration Modified	Rep:1137->200611.	[A] CELINE FONG
9	10 Jan 2022 10:30	Clm Veh Model Changed	(207022) AUDI A3 SPORTBACK 1.0 TFSI S TRONIC (LED) (A).	[A] CELINE FONG
10	10 Jan 2022 10:30	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CELINE FONG
11	10 Jan 2022 11:32	Adj Rpt Initiated		[A] HUEY YON
12	10 Jan 2022 11:32	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] HUEY YON
13	10 Jan 2022 11:32	Clm Dtl Modified	JPJ Reg. Date: -> 2019/06/27.	[A] HUEY YON
14	10 Jan 2022 11:32	Clm Details Notified		[A] HUEY YON
15	10 Jan 2022 15:36	Clm Registration Modified	Init.Est.:>5,000 - 6,000. Excess: -> 300.00. Excess Waived: -> 300.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Loo, Tong Shing
16	11 Jan 2022 09:17	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/01/19	[A] SHIAU CHAN

AUDIT TRAIL			
No.	On Audit	Remarks	By
17	11 Jan 2022 09:17 Adj Mandate Request	Cur.Req:22808.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	11 Jan 2022 10:06 Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/01/19. Mandate Remarks: Vehicle may commence repair - CLEAR Bonnet damaged photos to be uploaded. Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos	[I] Lim, Kok-Chong
19	11 Jan 2022 10:06 Adj Mandate Set	Approved:15808.00:Vehicle may commence repair - CLEAR Bonnet damaged photos to be uploaded. Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required	[I] Lim, Kok-Chong
20	13 Jan 2022 14:24 CIm Registration Modified	Acct Time:13:05:00->13:00:00.	[I] AIG OneClaim Integration User
21	13 Jan 2022 16:50 Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/01/19	[A] SHIAU CHAN
22	13 Jan 2022 16:50 Adj Mandate Request	Cur.Req:24729.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.	[A] SHIAU CHAN
23	13 Jan 2022 17:54 Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2022/01/19. Mandate Remarks: Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Merimen	[I] Lim, Kok-Chong
24	13 Jan 2022 17:54 Adj Mandate Set	Approved:17939.00: Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Merimen.	[I] Lim, Kok-Chong

Date From  **Date To**  **Audit Type**  **Go**

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2756089	10 Jan 2022 11:32:34	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKV995H		11.00