COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO

SHA4746E

DATE: 22.12.21

MAKE	TOYOTA		MVA .	JUMANI	_	
MODEL	PRIUS		DOA:	22. Dec. 2021	NTUC (Usum)
Qty	Parts Description/ Labou	ır	Туре	Unit Price	Amount] `
	1 REAR BUMPER ASSY			D 1	\$458.60	1
	1 REAR BUMPER CENTRE MLDG			P	\$552.60	
	1 REAR BUMPER BEAM			DT Q BE	\$318.80	* Pic
	1 REAR FLOOR UNDER COVER			1	1. \$220.50	XSVC
:	10 REAR BUMPER CLIPS			V):	(4 /\$22.00	
	1 REAR BUMPER SIDE U/COVER LH			1. else B	\$\$232.00	AMY XSU (
	1 REAR BUMPER SEAL COVER LH			- 4540 D	8 × \$148.40	XSUC
	1 REAR BUMPER RETAINER LH			n	ec /\$94.80	
	1 BOOTLID OUTER COVER	LVV Auto O			ut \$889.70	
	1 BOOTLID EMBLEM – PRIUS	LKK Auto Consi the Repairer of	Iltants hence	notify	\$60.80	
	1 BOOTLID EMBLEM – HYBRID	 To resurvey before 	lafter spray pain	iting	\$52.40	
	1 BOOTLID EMBLEM – STAR	 To display damage Parts prices are st 	d part(s) during	resurvey	\$52.90	
	1 BOOTLID COVER	 Third party survey 	is on a "Without	Prejudice" basis	\$1,128.60	
	1 TAILLAMP ASSY UPPER LH	No lilegal modifica	ion(s) is allowed	57	LX \$557.90	
	1 TAILLAMP ASSY LOWER LH	 Supplementary ite is subject to final a 	n(s) must be res oproval from inst		9 /\$548.40	
1	LO REAR END PANEL	Acknowledged by Re		70	\$602.10	KDIC
	1 REAR END PANEL GARNISH	Signature:	puller	D	\$ \$165.80	
	1 REAR WINDSCREEN GLASS – BIG	Tale:	the sales and a first second sales and	ne	/\$1,778.30	80
	1 REAR WINDSCREEN GLASS - SMAL	L		N.A	\$733.50	
					V	
			4	6)		
			2	, (]		
		SUB TOTAL	(\$8,618.10	1
		LESS 20%	X759	0	\$2,154.52	4
	DISCOL	JNTED TOTAL			\$6,463.58	SUSSICIAN
						7 12 - 29
	WINDSCREEN SEALANT			ne	\$46.00	NET
	BOOTLID COMFORT LOGO			Ne	\$30.00	NET
	BOOTLID COMFORT TEL.NOS LOGO			n	\$30.00	NET
	BOOTLID APPS LOGO			n	\$40.00	NET
	REVERSE SENSOR			(4)	\$180.00	NET
	REAR BUMPER MAT			nk	\$50.00	NET
	ADVERTISEMENT LOGO – FENDER			1	\$200.00	NET
	ADVERTISEMENT LOGO – BUMPER	e —		n	\$50.00	NET
	REMOVE/REFIX REAE WINDSCREEN	I GLASS		NK	\$120.00	NET
	REAR NUMBER PLATE			131	\$50.00	NET /
	1				\$796.00	V.
	Thrown E	Chhauta lou	^			1096
		35769				
	PANEL BEATING - 27/g	(21 1700			\$1,500.00	1050
= -	SPRAY PAINT	1 1			\$800.00	
	REMOVE/REFIX REVERSE SENSOR	L(S bolin at	ter repair k	photo	\$50.00	20
	CHECK WIRING	4 days w	12 /	2889	\$50.00	20 1
	TUFF KOTE	الم دل	V	ASMAS	\$50.00	30,/
	REMOVE/REFIX REAE WINDSCREEN	GLASS		10 118400	\$120.00	1/
						() ()

	THE PLANT OF THE P	PROPERTY OF THE STATE OF THE ST
12.12.21 1940 1940 - 2022	TOTAL LABOUR	\$2,570.00
Traines	ESTIMATE TOTAL	\$9,829.58
A DE BIE CORDE	19 AND 19	GHU ROOJE / ASR

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray peinting:

• To display damaged part(s) during resurvey:

• Parts prices are subject to confirmation:

• Third party survey is on a "Wilhout Prejudice" be.

• No illegal modification(s) a slowed:

• Supplementary ham(s) must be resurveyed and is subject to final approvintion insurance Coming surveyed and is subject to final approvintion insurance Coming.



10184.33

SUPPLEMENTARY OF PARTS AND LABOUR COSTS					
DESCRIPTION	QTY	ESTIMATE	REMARKS		
ANTENNA ELE.KEY	1	\$57.00	Curt		
TAILLAMP SIDE UNDER COVER	1	\$256.00	lut		
		V V			
		· · · · · · · · · · · · · · · · · · ·			
LABOUR					
DIAGNOSTIC AND RESET FAULT CODE		\$120.00	60		
		\			
	TOTAL:	\$433.00	JUMAN		