

Effective Date: 1 Nov 2020

LKK -

INSURANCE: NTUC (43)

MVA: L I M T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper	1		\$1,052.20 /
	Front Bumper Clips	10	\$2.20	\$22.00 ✓
	Front Bumper Side Bracket LH	1		\$22.40 ✓
	Headlamp LH	1		\$1,388.00 ✓
	SUB TOTAL			\$2,484.60
	LESS 20%			\$496.92
	DISCOUNTED SPARE PARTS TOTAL			\$1,987.68
	<u>Labour Charge</u>			
	Panel Beating			\$300.00
	Spray Painting Charge			\$300.00
	TOTAL LABOUR			\$600.00
	ESTIMATE TOTAL			\$2,587.68

Thuvan@Lihato.com

82235769

31/12/21 12:00

US/after repair photo

2 days w/ ✓

F: \$1100

repair days 2

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date: