

Date: 03.01.2022
 Vehicle No: SLD8081A
 Model: TESLA MODEL 3 PERFORMANCE
 Chassis: LRW3F7EL5MC263562
 Reg.Year: 2021

Third Party Insurer: EQ
 Third Party Veh No: SNB4444A
 Date of Accident: 31.12.2022
 Estimator: Victor
 Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR RH	1		\$1,009.35
SUB TOTAL				\$1,009.35
LESS 10%				-\$100.94
PARTS TOTAL				\$908.42

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	CERAMIC COATING	1		\$500.00
S/N TOTAL				\$500.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR & READJUST ACCIDENT AREA. \$400.00 *Pol*

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA. \$400.00 *✓*

TO CHECK WIRING & ELECTRICAL SYSTEM. *na* \$150.00 *X*

TO DIAGNOS FAULT CODE & RESET MEMORY. *na* \$200.00 *X*

Not Authorize

LABOUR TOTAL \$1,150.00

TOTAL \$2,558.42

2 days