

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 1 of 5

Estimate No. : b1 60555
Date Estimated : 10/01/2022
Prepared By : Foong Shiuh Jye

- ESTIMATE REPAIR FOR -

Xu Shuzheng
56 Edgedale Plains
#03-11

Singapore 828822

- ACCOUNT - 158

Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNA2765S	WBA72AG040CG04380	15/06/2021	520i Sedan	12

DESCRIPTION

To replace front bumper including to knock out dented area caused by the accident

To respray front bumper

To replace left headlight.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

To check electrical wiring system at the front section for proper function including adjustment of headlights.

Sundries.

VALUE

850 1,275.00

986 1,058.00

Xnn? 456 481.00

168 177.00

168 177.00

80/? 150.00

Total Labour 1: 3,298.00

DESCRIPTION

LH RUBBER STRIP (BASIS) ? ms
LH GRILLE COVER Xnn
IMPACT ABSORBER TOP (ECE) ? Xnn
FRT BUMPER PANEL PRIMED (PDC) soc
FRONT GRILLE (BASIS) ? se
GRID CENTRE (BASIS) ? Xnn
LH GRILLE AIR INLET OPEN (BA) ? Xnn
AIR FLAPS TOP ? Xnn
AIR FLAPS BOTTOM ? Xnn
AIR DUCT RADIATOR BOTTOM ? Xnn
LH HEADLIGHT LED AHL ? Xnn

QTY	PRIC	VALUE
1	38.25	38.25
1	83.60	83.60
1	75.00	75.00
1	1,405.95	1,405.95
1	351.40	351.40
1	97.50	97.50
1	83.60	83.60
1	287.25	287.25
1	273.55	273.55
1	78.10	78.10
1	4,654.85	4,654.85

Total Parts : 7,429.05

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 2 of 5

Estimate No. : b1 60555
Date Estimated : 10/01/2022
Prepared By : Foong Shiuh Jye

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNA2765S	WBA72AG040CG04380	15/06/2021	520i Sedan	12

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 21/02/22 @ 11:25 Excess S\$ _____
Surveyor's Name Rafael Sign _____
Surveyor's Tel 90010068 Authorised Yes / No
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No
Surveyor's E-mail _____
No. of Working Days Recommend 3 days

Reg before print

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	3,298.00
Parts	:	7,429.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	750.89
Grand Total	:	11,477.94