



Service Request Details

Claim

S1M03PMA

Reference

CS/ASM22000344/Aqy3 

Loss Date

27 December 2021

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

29 Dec 2021 9:56:08 AM

Request Date

11 January 2022

Due Date

11 January 2023

Services

Pre-Repair Survey

Actions

Next Step

Finish the work

Complete Work

Vehicle Information

Incident Vehicle Registration #
GBE3547U

Make
TPVD - Toyota

Model
Dyna

Service Address

, , ,

Primary Contact/Insured

LOO JOO SONG
BLK 10C BENDEMEER ROAD, #30-125, 333010, Singapore
82826825
maxloothor@hotmail.com

Claim Handler

KHONG Lynn

lynn.khong@axa.com.sg

Additional Instructions

Messages3

Invoices

History

Documents 1

Assessment

Metrics

Notes

New Message

TYPE



SENT

29/3/22 9:38 AM

BODY

Dear Lynn, we will check the matter with our surve...



TYPE



SENT

29/3/22 9:18 AM

FROM

KHONG Lynn

SUBJECT

Re:TP WP IA OF VEHICLE GBE 3547U UPLOADED

BODY

Hi Shiau Chan, TP lawyer has submitted LOD, as lin...



TYPE



SENT

21/3/22 10:30 AM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

TP WP IA OF VEHICLE GBE 3547U UPLOADED

BODY

Dear Lynn, please be informed that the TP WP IA of...



TYPE



SENT

10/3/22 9:28 PM

FROM

KHONG Lynn

SUBJECT

TP SUR STATUS

BODY

Hi, please check for long o/s survey arrangement. ...



TYPE



SENT

11/1/22 12:54 PM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

VNI

BODY

Dear Ms Khor, please be informed that the vehicle ...



