

ASS. REC. BY:

REF:

C72/ 220083581K7

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7-8

days

Res.: Yes or No

Lum Sum:

1-B.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PM E 482L

Yr Regn:

09, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius +

c.c.

1798

Colour

M. Red

A/C:

Insured / Std / NI / NA

Sp. Reading

34783

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTD8P3EU40J032300

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/80R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fines

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Notified
Returning B4pprim
7-8 days

ESTIMATE

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD #15-00
SPRINGLEAF TOWER
SINGAPORE 079909
ATTN: ACCIDENT CLAIMS DEPARTMENT

DATE : 10.01.2022
VEHICLE NO : SME482L
VEH MAKE/MODEL : TOYOTA PRIUS PLUS
YOM : 2018
CHASSIS NO : JTDZS3EU40J032300
DATE OF ACCIDENT : 08.01.2022

NO	QTY	DESCRIPTION	AMOUNT \$
		<u>LIST PRICE:-</u>	
1	1	REAR TAIL GATE <i>Hit</i>	
2	1	REAR TAIL GATE LOCK <i>R</i>	
3	1	REAR TAIL GATE LOGO <i>nanx</i>	
4	1	REAR TAIL GATE LOGO "PRIUS+" <i>Rec</i>	
5	1	REAR TAIL GATE LOGO "HYBRID" <i>Rec</i>	
6	1	REAR TAILGATE CENTRE PANEL <i>?</i>	
7	1	REAR TAIL GATE INNER TRIM BOARD <i>Pnx</i>	
8	1	REAR LAMP LH <i>Pnx</i>	
9	1	REAR LAMP LOWER BRACKET LH <i>OMA</i>	
10	1	REAR LAMP RH <i>Pnx</i>	
11	1	REAR LAMP LOWER BRACKET RH <i>Pnx</i>	
12	1	REAR BUMPER <i>Brc</i>	
13	2	REAR BUMPER SIDE RETAINER <i>hit</i>	
14	1	REAR BUMPER LOWER <i>nd</i>	
15	1	REAR REFLECTOR LH <i>Pnx</i>	
16	1	REAR REFLECTOR RH <i>Pnx</i>	
17	1	REAR WEATHERDIELD <i>Pnx</i>	
18	1	REAR END PANEL <i>?</i>	
19	1	REAR END PANEL GARNISH <i>?</i>	
20	SET	REAR TAIL GALTE GLASS MOULDING <i>Rec</i>	
21	1	REAR FENDER LH <i>R x</i>	
22	1	REAR FENDER SHIELD LH <i>Pnx</i>	
23	1	REAR FENDER RH <i>R x</i>	
24	1	REAR FENDER SIELD RH <i>Pnx</i>	
25	1	FRONT BONNET <i>R1</i>	
26	2	FRONT BONNET HINGE <i>?</i>	
27	1	FRONT HEADLAMP LH <i>mgc</i>	
28	1	FRONT HEADLAMP LOWER BRACKET LH <i>?</i>	
29	1	FRONT HEADLAMP RH <i>mgc</i>	
30	1	FRONT HEADLAMP LOWER BRACKET RH <i>?</i>	
31	1	FRONT BUMPER <i>Bt</i>	
TOTAL - LIST ITEM			\$ -
LIST 25%			\$ -
TOTAL			\$ -

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD #15-00
SPRINGLEAF TOWER
SINGAPORE 079909
ATTN: ACCIDENT CLAIMS DEPARTMENT

DATE : 10.01.2022
VEHICLE NO : SME482L
VEH MAKE/MODEL : TOYOTA PRIUS PLUS
YOM : 2018
CHASSIS NO : JTDZS3EU40J032300
DATE OF ACCIDENT : 08.01.2022

NO	QTY	DESCRIPTION	AMOUNT \$
34	1	FRONT GRILLE CENTRE <i>CM ✓</i>	
36	1	FRONT GRILLE LOWER <i>rx</i>	
37	1	FRONT EMBLEM <i>rx</i>	
38	1	FRONT FOG LAMP LH <i>rx</i>	
39	1	FRONT FOG LAMP RH <i>rx</i>	
40	1	FRONT SIGNAL LAMP LH *BUMPER <i>rx</i>	
41	1	FRONT SIGNAL LAMP RH *BUMPER <i>rx</i>	
42	1	FRONT REINFORCEMENT <i>rx</i>	
43	2	FRONT REINFORCEMER ARM <i>rx</i>	
44	1	FRONT SUPORT PANEL <i>?</i>	
45	1	FRONT NUMBER PLATE GARNISH <i>NIP X</i>	
46			
47			
48			
49			
TOTAL - LIST ITEM			\$ -
LIST 25%			\$ -
TOTAL			\$ -

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD #15-00
SPRINGLEAF TOWER
SINGAPORE 079909
ATTN: ACCIDENT CLAIMS DEPARTMENT

DATE : 10.01.2022
VEHICLE NO : SME482L
VEH MAKE/MODEL : TOYOTA PRIUS PLUS
YOM : 2018
CHASSIS NO : JTDZS3EU40J032300
DATE OF ACCIDENT : 08.01.2022

NO	QTY	DESCRIPTION	AMOUNT \$
		SPECIAL NETT ITEMS:-	
1	1	REVERSE SENSOR	\$ 360.00
2	SET	REAR BUMPER CLIPS & REAR FENDER SHIELD CLIPS	\$ 60.00
3	2 SET	REAR END PANEL GARNISH CLIPS	\$ 45.00
4	SET	REAR TAILGATE GLASS SEALANT	\$ 80.00
	SET	REAR NUMBER PLATE WITH FRAME	\$ 50.00
	SET	FRONT BUMPER & FRONT FENDER SHIELD CLIPS	\$ 60.00
	SET	FRONT NUBMBER PLATE WITH FRAME	\$ 50.00
Total - SN Item			\$ 705.00
		Labour Charges:-	
1		SPRAY PAINT ON ALL AFFECTED AREA (FRONT & REAR)	\$ 1,000.00
2		LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	\$ 1,000.00
3		TO CHECK WIRING SYSTEM & LIGHT	\$ 100.00
		TO APPLY ANTI RUST TREATMENT	\$ 120.00
4		TO REMOVE/REFIX REVERSE SENSOR	\$ 150.00
5		TO REMOVE/REFIX REAR INNER COMPARTMENT TO FACILITIES REPAIR	\$ 150.00
6		TO REMOVE/REFIX REAR TAILGATE, TOP SPOILER, WIPER MOTOR, MECHEMISM & ETC TO NEW TAILGATE	\$ 300.00
7		TO CHECK WATER LEAKING	\$ 150.00
8		TO REMOVE/REFIX/REPLACE REVERSE SENSOR	\$ 180.00
Total - L/C			\$ 3,150.00
Sub-Total			\$ 3,855.00
7% GST			\$ 269.85
Total			\$ 4,124.85

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 08/01/2022 17:19 (SGT)
Date of Accident 08/01/2022 14:45 (SGT)
Exact Location of Accident Braddell Rd, Singapore
Additional Location Information Along Braddell Rd Twd Toa Payoh Flyover
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SME482L

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner Sriram Venkata Musunuri
NRIC No SXXXX694C
Email Address sriram.musunuri@gmail.com
Mobile Phone No (Phone) +65-98272973
Alternative Phone No +65-93855365

VEHICLE PARTICULARS

Manufacturer Toyota
Model Prius
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1600


INSURANCE COMPANY

Name of Insurance Company HL Assurance Pte Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number MP319014
Cover Note Number -

DRIVER

Name of Driver Musunuri Rajalakshmi
NRIC No SXXXX682A

Sketch Plan



Describe Circumstances of the Accident

Location: <u>Along Braddell Rd twd Toa Payoh Flyover</u>		
Date of Accident: <u>21/12</u>	Time of Accident: <u>14:45hr</u>	
Vehicle A: <u>3ME432L</u>	Vehicle B: <u>SMJ 5061J</u>	Vehicle C: <u>SMC 1748A</u>
Traveling along Braddell Rd twd Toa Payoh Flyover. I saw infant vehicle suddenly brake to a complete stop, so I merge to a complete stop to brake. Suddenly I felt a huge impact from my rear, Veh B had collided into my car, as the impact was too huge my car dash smashed & collided into Veh C.		

Declaration

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature / Date & Time


 Driver's Signature (If driver is not the policyholder) / Date & Time


 Witnessed by Reporting Centre Personnel

07 JAN 2022