



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Ref: CS3/ASM22000361/y3	
			Date: 11/01/2022	
			Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SHC 5542J		Veh. Inspected	SJR 840D
Policy No.			Coverage (\$)	0.00
Claim No.	S2M03QR7		Excess (\$)	0.00
Assign From	WINNIE HO (SMART CLAIMS)		Assign Date	11/01/2022
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre				mm
L/H Front Tyre				mm
R/H Rear Tyre				mm
L/H Rear Tyre				mm
4. Description of Damages				
5. General Information				
Accident Date	10/01/2022		Inspection Date	
Survey held at	HIAP LEK AUTOMOBILE TRADING BLK 14 #01-19 SECTOR B SIN MING INDUSTRIAL ESTATE . SINGAPORE 575658.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				