

Shiau Chan (LKKAUTO)

From: Simon Ho (LKKAUTO)
Sent: Friday, 25 February 2022 9:01 AM
To: Shiau Chan (LKKAUTO)
Subject: Re: SMRT-TP SMN 6785B SURVEYED BY STEVE (OUR REF: CS/SMR22000380/Eqy3)

Dear Shiau Chan,

AUDIT CHECK DONE FOR SMN6785B, FOUND NOT ECONOMICAL TO REPAIR & SOME PARTS PRICES NEED VERIFICATION.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Thursday, 24 February 2022 5:42 pm
To: Simon Ho (LKKAUTO) <SimonHo@lkkauto.com>
Subject: SMRT-TP SMN 6785B SURVEYED BY STEVE (OUR REF: CS/SMR22000380/Eqy3)

Dear Simon,

For your audit.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)