

Your Ref : SNM22D200042/C01/CHEESC

Date: 19th Jan 2022

Our Ref : CS/CTI22000381/Uqy3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SJC 7461Y
ACCIDENT ON 02/01/2022**

Instruction was received to inspect the vehicle Reg. No. SJC 7461Y. The inspection was conducted on 12/01/2022 at the premises of M/s Car City Auto Centre Pte Ltd, Blk 9006 #01-198, Tampines Street 93, Singapore 528840.

The following vehicle information was recorded:

Registration Number	: SJC 7461Y
Make/Model	: Mitsubishi Lancer 1.6 M
Year of Registration	: 2008
Body Colour	: Blue
Chassis Number	: JMYSNCS3A8U003482
Engine Capacity	: 1584 cc

The vehicle sustained damages at the front n/s, n/s rear and o/s rear portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 7,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 4,751.00
Nett Liability	<u>S\$ 2,249.00</u> =====

Vehicle Inspected By:



CHUA KANG SENG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.