

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chee So Chow

Date: 13 Jan 2022

Preliminary Advice

Vehicle No	: SJC7461Y	Accident Date	: 02/01/2022
Make	: MITSUBISHI LANCER	Policy No.	: DMPCSNA00041552105
Assignment Date	: 11/01/2022	Excess	: S\$500.00
Date of Inspection	: 12/01/2022	Est. Duration of Repair	: 0
Inspection At	: CAR CITY AUTO CENTRE PTE LTD (HQ) BLK 9006 #01-198, TAMPINES STREET 93 SINGAPORE 528840		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
-------------------	------

Pre-Accident Value	:S\$	7,000.00
COE / PARF Rebate	:S\$	4,751.00
Salvage Value	:S\$	
Margin for Repair	:S\$	2,249.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :