

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0023/2021/JT

14-Jan-22

CHANG

1 of 1

SLX 2317 E

AUDI Q3 1.4 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	FRONT WHEEL HOUSING LINER - RH <i>torn</i>	1 208 \$ 260.00	<i>lls</i>
2	HEADLIGHT MOUNTING - RH <i>crack</i>	1 105.20 \$ 132.00	
3	BONNET RELEASE ELEMENT <i>damaged</i>	1 51.44 \$ 65.00	
GRAND TOTAL		\$ 457.00	



For Premium Automobiles Pte Ltd

Adrian Ling
29/01/22

lls

*To add 3 repair days
for the replacement
of lock carrier.*


lls

Authorised Signature



PREMIUM AUTOMOBILES



SUB, ROAD 1 SINGAPORE 406699
TEL 6366 1323 FAX 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CUMME@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLX 2317 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	750
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL AND CONTROL UNIT. PRESSURISE COOLING SYSTEM VACUUM AND REGAS	S/N \$ 2,200.00	h/s. R1234 Air Con gas utilised.
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDERS AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 4,800.00	500 + 1500. h/s.
5	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$ 2,500.00	550
6	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	X
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	192
TOTAL LABOUR CHARGES		\$ 11,044.00	

+ 3 days

Car-in

14/1/22

wip: 62734

L2/Hong

PREMIUM AUTOMOBILES

5, UBI ROAD 1 SINGAPORE 408699

TEL: 6366 320 FAX: 6821 1103

EMAIL: NORA.FHA@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

A2G - Adrian

- 3 days.


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 2317 E

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER Distorted	1	S	1,008.00	✓
2	FRONT BUMPER CONNECTING PIECE	1	S	145.00	✓
3	FRONT BUMPER CLOSING ELEMENT - LH	1	S	59.00	✓
4	FRONT BUMPER GRILLE - CENTER	1	S	217.00	✓
5	FRONT BUMPER GRILLE COVER - LOWER	1	S	51.00	✓
6	FRONT BUMPER GRILLE - LH	1	S	110.00	✓
7	FRONT BUMPER CLOSING ELEMENT	1	S	190.00	✓
8	FRONT BUMPER SPOILER	1	S	383.00	✓
9	FRONT BUMPER BRACKET	1	S	21.00	✓
10	FRONT BUMPER AIR GUIDE GRILLE - LH	1	S	153.00	✓
11	RADIATOR GRILLE	1	S	1,433.00	✓
12	RADIATOR STRIKER PLATE	1	S	244.00	✓
13	RADIATOR COVER CAP	1	S	45.00	✓
14	"360" CAMERA	1	S	1,141.00	✓
15	FRONT BUMPER FOAM FILLER PIECE	1	S	102.00	✓
* - 16	FRONT BUMPER REINFORCEMENT BEAM	1	S	916.00	✓
17	FRONT BUMPER GUIDE SECTION - LH	1	S	39.00	✓
18	FRONT BUMPER TOP COVER	1	S	123.00	✓
19	"CAUTION" STICKER	1	S	14.00	✓
20	AIR COND STICKER	1	S	9.00	✓
SUB TOTAL SPARE PARTS		:	\$	6,402.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES




55 UBI ROAD 1 SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NDRA.FHA1@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 2317 E

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT PARKING AID SENSOR	2	TBC		
22	FRONT PARKING AID SENSOR SEAL RING	4	\$ 9.00		
23	FRONT BUMPER WIRING SET	1	\$ 676.00		
24	HORN - LH	1	\$ 137.00		
25	HORN SUPPORT - LH	1	\$ 22.00		
26	FRONT FENDER - LH	1	\$ 1,206.00		
27	FRONT FENDER BRACE - LH	1	\$ 88.00		
28	FRONT FENDER BRACKET - LH	1	\$ 32.00		
29	FRONT WHEEL HOUSING LINER - LH	1	\$ 240.00		
30	FRONT WHEEL HOUSING LINER COVER - LH	1	\$ 16.00		
31	HEADLIGHT MOUNTING - LH	1	\$ 118.00		
32	HEADLIGHT - LH	1	\$ 5,589.00		
33	LIFT CYLINDER - LH	1	\$ 210.00		
34	LIFT CYLINDER HOSE	1	\$ 80.00		
35	WATER RESERVOIR	1	\$ 220.00		
36	LOCK CARRIER	1	\$ 1,272.00		
37	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 7.00		
38	A/C CONDENSER	1	\$ 551.00		
39	RADIATOR COOLANT	6	\$ 266.00		
40	RADIATOR AIR GUIDE - LH	1	\$ 38.00		
SUB TOTAL SPARE PARTS			\$ 10,857.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST.
LEC IND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1 SINGAPORE 408659
 TEL 6366 2323 FAX 6841 1183
 EMAIL NORA.KHAIR@PREMIUMAUTO.COM.SG CLAIM@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 2317 E

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	RADIATOR AIR GUIDE - UPPER / LOWER <i>Defund</i>	2	\$	84.00	✓
42	FRONT WHEEL ARCH COVER - LH / RH <i>LH 1, RH 1</i>	2	\$	536.00	✓
43	FRONT NOISE INSULATION <i>11/12</i>	1	\$	397.00	✓
44	FRONT NO PLATE <i>11/12</i>	S/N	\$	60.00	✓
45	SUNDRIES		\$	350.00	
TOTAL SPARE PARTS		:	\$	18,686.00	
TOTAL LABOUR CHARGES		:	\$	11,044.00	
GRAND TOTAL		:	\$	29,730.00	

ALL CHARGES ARE NOT INC USIVE OF GST
 (LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT