

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0023/2021/JT
DATE : 10-Jan-22
WIP : 62734

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 11/1/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

6 days - ok - Jy - 14 Mar 22

OWNER'S NAME : MS CHUA JIA MIN
ADDRESS : 1 FERNSLE CLOSE
#19-01
SINGAPORE 797485
TELEPHONE : HP +65 82884029
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210105202
VEHICLE NO : **SLX 2317 E**
MODEL CODE : AUDI Q3 1.4 TFSI S
MODEL YEAR : 31/08/2021
ENGINE NO : CZD C49833
CHASSIS NO : WAUZZZF30M1155597
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 09-Jan-22
PLACE OF ACCIDENT : SENGKANG EAST ROAD
U-TURN

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLX 2317 E

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL AND CONTROL UNIT. PRESSURISE COOLING SYSTEM, VACUUM AND REGAS.	S/N \$	2,200.00	\$	2,200.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDERS AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSTION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,800.00	\$	2,000.00
5	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,500.00	\$	550.00
6	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$	280.00		
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 11,044.00	\$	5,672.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SLX 2317 E

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT		REMARKS
1	FRONT BUMPER	1	\$ 1,008.00	\$	806.40
2	FRONT BUMPER CONNECTING PIECE	1	\$ 145.00	\$	115.60
3	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 59.00	\$	46.64
4	FRONT BUMPER GRILLE - CENTER	1	\$ 217.00	\$	173.20
5	FRONT BUMPER GRILLE COVER - LOWER	1	\$ 51.00		
6	FRONT BUMPER GRILLE - LH	1	\$ 110.00	\$	88.00
7	FRONT BUMPER CLOSING ELEMENT	1	\$ 190.00	\$	151.60
8	FRONT BUMPER SPOILER	1	\$ 383.00	\$	306.40
9	FRONT BUMPER BRACKET	1	\$ 21.00		
10	FRONT BUMPER AIR GRUIDE GRILLE - LH	1	\$ 153.00	\$	122.00
11	RADIATOR GRILLE	1	\$ 1,433.00	\$	1,146.40
12	RADIATOR STRIKER PLATE	1	\$ 244.00	\$	194.80
13	RADIATOR COVER CAP	1	\$ 45.00		
14	"360" CAMERA	1	\$ 1,141.00		
15	FRONT BUMPER FOAM FILLER PIECE	1	\$ 102.00		
16	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 916.00	\$	732.40
17	FRONT BUMPER GUIDE SECTION - LH	1	\$ 39.00		
18	FRONT BUMPER TOP COVER	1	\$ 123.00	\$	98.00
19	"CAUTION" STICKER	1	\$ 14.00	\$	10.88
20	AIR COND STICKER	1	\$ 8.00	\$	5.68
SUB TOTAL SPARE PARTS		:	\$ 6,402.00	\$	3,998.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SLX 2317 E

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	3,998.00
21	FRONT PARKING AID SENSOR	2	TBC		
22	FRONT PARKING AID SENSOR SEAL RING	4	\$ 9.00		
23	FRONT BUMPER WIRING SET	1	\$ 676.00		
24	HORN - LH	1	\$ 137.00	\$	109.60
25	HORN SUPPORT - LH	1	\$ 22.00	\$	17.04
26	FRONT FENDER - LH	1	\$ 1,286.00		
27	FRONT FENDER BRACE - LH	1	\$ 88.00		
28	FRONT FENDER BRACKET - LH	1	\$ 32.00		
29	FRONT WHEEL HOUSING LINER - LH	1	\$ 240.00	\$	191.60
30	FRONT WHEEL HOUSING LINER COVER - LH	1	\$ 16.00		
31	HEADLIGHT MOUNTING - LH	1	\$ 118.00	\$	94.40
32	HEADLIGHT - LH	1	\$ 5,589.00	\$	4,471.20
33	LIFT CYLINDER - LH	1	\$ 210.00	\$	167.60
34	LIFT CYLINDER HOSE	1	\$ 80.00	\$	63.44
35	WATER RESERVOIR	1	\$ 220.00	\$	176.00
36	LOCK CARRIER	1	\$ 1,272.00	\$	1,017.60
37	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 7.00		
38	A/C CONDENSER	1	\$ 551.00		
39	RADIATOR COOLANT	6	\$ 266.00	\$	212.64
40	RADIATOR AIR GUIDE - LH	1	\$ 38.00	\$	29.76
SUB TOTAL SPARE PARTS		:	\$ 10,857.00	\$	10,548.88

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 2317 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 10,548.88
41	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 84.00	\$ 66.08
42	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 536.00	\$ 428.80
43	FRONT NOISE INSULATION	1	\$ 397.00	
44	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
45	SUPPLEMENTARY		\$ 457.00	\$ 364.64
46	SUNDRIES		\$ 350.00	
TOTAL SPARE PARTS		:	\$ 19,143.00	\$ 11,468.40
TOTAL LABOUR CHARGES		:	\$ 11,044.00	\$ 5,672.00
GRAND TOTAL		:	\$ 30,187.00	\$ 17,140.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-25/02/22



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0023/2021/JT 14-Jan-22 CHANG 1 of 1 SLX 2317 E AUDI Q3 1.4 TFSI	
Quantity	Description		Unit Price	Amount
Parts				
1	FRONT WHEEL HOUSING LINER - RH	1	\$ 260.00	\$ 208.00
2	HEADLIGHT MOUNTING - RH	1	\$ 132.00	\$ 105.20
3	BONNET RELEASE ELEMENT	1	\$ 65.00	\$ 51.44
GRAND TOTAL			\$ 457.00	\$ 364.64

For Premium Automobiles Pte Ltd

Authorised Signature