

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find Next
---	---	---	--------	---	---	---	---	------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HL ASSURANCE PTE LTD 11 KEPPEL ROAD #11-01 ABI PLAZASINGAPORE 089057		Ref: CS/HLA22000405/Eqf3 Date: 12/01/2022 Code: HLA	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SBZ 312P	Veh. Inspected	SLP 2755R
Policy No.	MP317436	Coverage (\$)	0.00
Claim No.	MPC03093	Excess (\$)	0.00
Assign From	MERIMEN (JOEL GOH ZAN WEI)	Assign Date	12/01/2022
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	09/01/2022	Inspection Date	13/01/2022
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 247 ALEXANDRA ROAD SINGAPORE 159934		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			