



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22000406/Bvf3n2	
			Date: 22/02/2022	
			Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMK 273S	Veh. Inspected	SGK 2019T
	Policy No.		Coverage (\$)	0.00
	Claim No.	BISAISCL2022-00387FQ	Excess (\$)	0.00
	Assign From	SHANTI	Assign Date	12/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA CIVIC IMA	c.c	1339
	Engine No.	HIDDEN	Year of Reg.	2006
	Chassis No.	JHMF36206S203078	Colour	BLACK
	Odometer	384838 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	WINDFORCE	5 mm
	L/H Front Tyre	195/65 R15	WINDFORCE	5 mm
	R/H Rear Tyre	195/65 R15	BRIDGESTONE	5 mm
	L/H Rear Tyre	195/65 R15	BRIDGESTONE	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/01/2022	Inspection Date	12/01/2022
	Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	