

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592

Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

User ID PohSuan

Section A - Accident Details						
Registration Number	SHB5705L					
Case Reference Number	TAX/01/22/2015					
Registration Date	4/3/2016					
Company Type	Strides Taxi Pte Ltd					
Make	ТОУОТА					
Model	PRIUS					
Name of Driver	SIM KWONG MIANG					
Type of Accident	Head to Rear					
Accident Date and Time	10/1/2022 7:03 AM					
Accident Reported Date and Time	10/1/2022 12:02 PM					
Is Surveyor Required?	Yes					
Survey by						
Vehicle is Towed Back?	No					
Towed Back Date and Time						
Replacement Vehicle issued?	No					
Job Card Number	24113610					
Special Instruction to ARC,if any	REAR PORTION					
Prepared Date and Time	10/1/2022 2:18 PM					
Chassis Number						
Mileage						
Work Shop						
Repair Completion Date and Time						

Summary of Repair Estimat	es	
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$738.00	\$300.00
Total Spare Part Cost	\$1,855.73	\$551.82
Total Other Cost	\$360.00	\$40.00
TOTAL COST	\$3,460.73	\$1,091.82
Lump Sum Total	\$3,450.00	\$1,100.00 (L/S)
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / China Taiping
ARC / Surveyor Sign Off Date	18/01/2022 9:13 AM	18/01/2022 9:03 AM
Signature		Red
Remarks	Total number of repair days = 3 days. SUP = + 1 days.	lump sum repair / resurvey after repai



STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 31/01/2022 User ID PohSuan

Section C - Quotation and Accident Invoice Details					
Quotation Number	QN-2201-0431	Invoice Number			
Quotation Date	31.01.2022	Invoice Date			
Invoice Amount		Prepared Date			

Section D - Details of Repair Estimates					
Part 1 - Labour Works					
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable			
TO REPAIR REAR PORTION	\$507.00	\$200.00			
Total Labour	\$507.00	\$200.00			

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO RESPRAY REAR BUMPER	\$378.00	\$200.00		
TO RESPRAY REAR BUMPER REINFORCEMENT	\$180.00	\$0.00		
TO RESPRAY REAR BUMPER REINFORCEMENT	\$180.00	\$100.00		
Total Spray Painting & Panel Beating	\$738.00	\$300.00		

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$40.00		
O REPLACE SUNDRY PARTS	\$100.00	\$0.00		
O CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00		
O WASH AND VACUUM	\$60.00	\$0.00		
Total Other Costs	\$360.00	\$40.00		

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159- 47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		89997- 30070	ANTENNA,ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Check
		52576- 47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given
		52575- 47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given
		76088- 47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given
		76087- 47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given
		58308- 47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given
		51442- 12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Not Given
		52023- 12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check
		76891- 47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check
		90467- 07211	BUMPER CLIPS	10.00	\$2.10	25.00	\$15.75	Replace	Replace
		52016- 47030	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check
		52016- 47030	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check
Total					\$2,470.20		\$359.70		



STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 31/01/2022 User ID PohSuan

Part	Portion	Stock	Part Name	Quantity	List Price \$	Discount	Final Price	ARC	Surveyor
Number		Number				(%)	(\$)	Check	Check
		52576-	BUMPER SIDE RETAINER	1.00	\$94.80	25.00	\$71.10	Replace	Replace
		47020	RR/LH						
		76088-	BUMPER LIP COVER RR/LH	1.00	\$72.20	100.00	\$0.00	Replace	Old Damage
		47020						'	
		52023-	BUMPER REINFORCEMENT	1.00	\$205.70	25.00	\$154.27	Replace	Replace
		12240	REAR						
		52016-	ARM SUB-ASSY, RR	1.00	\$139.60	25.00	\$104.70	Replace	Replace
		47030	BUMPER LH					'	
Γotal					512.30		330.07		

	689.78	
	-20%	
	551.82	
	200.00	L/S \$1,100/-
	340.00	
_	1,091.82	