

1

of 2 ?

100%

▼

Find

Next

LKK

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HL ASSURANCE PTE LTD

11 KEPPEL ROAD

#11-01 ABI PLAZASINGAPORE 089057

Ref: CS/HLA22000465/Evf3

Date: 13/01/2022

Code: HLA

1. Policy Particulars :- OWN DAMAGE

Insured Veh.

Veh. Inspected

MP301419

SKV 7288U

Policy No.

Coverage (\$)

MP301419

0.00

Claim No.

Excess (\$)

MPC03096/OD

0.00

Assign From

Assign Date

MERIMEN (WONG WEE FU)

13/01/2022

2. Vehicle Particulars & Condition

Make & Model

c.c

HIDDEN

0

Engine No.

Year of Reg.

HIDDEN

Chassis No.

Colour

Odometer

Steering

-

Brakes

Modification

General

3. Conditions of Tyres

Size

Make

Balance

R/H Front Tyre

mm

L/H Front Tyre

mm

R/H Rear Tyre

mm

L/H Rear Tyre

mm

4. Description of Damages

5. General Information

Accident Date

11/01/2022

Inspection Date

14/01/2022

Survey held at

ACCORD AUTO SERVICES PTE LTD

10 ANG MO KIO INDUSTRIAL PARK

2A AMK AUTO POINT #03-11

SINGAPORE 568047

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)

B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

https://views.init.com.sg/report/reportserver?Report=LKKInspection&From=344112&rs:Command=Render&rc:Parameters=false&rc:Zoom=Page ...

1/1