



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Policy: 21/21/22/VC05/025346

Date: 21<sup>th</sup> January 2022

Our Ref: CS/LPC222000467/T1qf3

The Motor Claims Department  
Lonpac Insurance Bhd

Dear Sirs/Mdm

**PRELIMINARY ADVICE OF VEHICLE NO. XE 957D .**


We thank you for the instruction on 13/01/2022.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/01/2022 at the premises of M/s WOON MENG MOTOR PTE LTD and have the following to report:-

|                          |       |                  |   |
|--------------------------|-------|------------------|---|
| Workshop Estimate Amount | : S\$ | <u>66,345.45</u> | . |
| Revised Estimate Amount  | : S\$ | <u>36,830.95</u> | . |
| "Check" Items Amount     | : S\$ | <u>24,859.50</u> | . |
| Market Value             | : S\$ | <u>56,000.00</u> | . |
| LTA Reimbursement Value  | : S\$ | <u>5,887.00</u>  | . |
| Nett Value               | : S\$ | <u>50,113.00</u> | . |

Description of Damage:

The vehicle sustained damages at the front o/s, front n/s portion, undercarriage and rooftop.



Comments/ Present Status:

Damages consistent.

Repair cost economical.

Repairer willing to undertake the repair cost not more than \$50,000.00 on Lump Sum basis.

Recommend days of repair: 21 repair days

We have not authorize repair.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.

Yours faithfully

Mohd Taufikh  
Automotive Assessor