



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Ref: CS3/ASM22000481/Gty3	
			Date: 13/01/2022	
			Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SH 9292Y	Veh. Inspected	FBQ 6983K	
Policy No.		Coverage (\$)	0.00	
Claim No.	S2M03QVM	Excess (\$)	0.00	
Assign From	VALE OH (SMART CLAIMS)	Assign Date	13/01/2022	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	04/01/2022	Inspection Date	13/01/2022	
Survey held at	EQUATOR BROTHERHOOD 25 KAKI BUKIT ROAD 4 #03-19 SYNERGY @KB SINGAPORE 417800			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				