



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22000486/Kqf3e2	
			Date: 11/02/2022	
			Code: AIS	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SKM 395L
	Policy No.	SP2000133049-01	Coverage (\$)	0.00
	Claim No.	2022 22003683SL	Excess (\$)	600.00
	Assign From	SHANTI	Assign Date	13/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	PEUGEOT 5008 (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	VF30E5FVADS136486	Colour	METALLIC BLACK
	Odometer	119532 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55 R16	TOURADOR	8 mm
	L/H Front Tyre	215/55 R16	TOURADOR	8 mm
	R/H Rear Tyre	215/55 R16	TOYO	4 mm
	L/H Rear Tyre	215/55 R16	TOYO	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	31/12/2021	Inspection Date	18/01/2022
	Survey held at	DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645		
5a. Remarks				
	A)THE MARKET VALUE IS S\$34,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			