



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22000512/Etf3e2	
			Date: 26/01/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMB 1430X	Veh. Inspected	SG 6003R
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22000157MFBP	Excess (\$)	0.00
	Assign From	AINI BINTE	Assign Date	14/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	MAN A95	c.c	10518
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	WMAA95ZZ6JF007920	Colour	GREEN
	Odometer	189740 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	295/80 R22.5	DUNLOP	4 mm
	L/H Front Tyre	295/80 R22.5	DUNLOP	4 mm
	R/H Rear Tyre	295/80 R22.5 (D)	DUNLOP	4/4 mm
	L/H Rear Tyre	295/80 R22.5 (D)	DUNLOP	4/4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/01/2022	Inspection Date	14/01/2022
	Survey held at	Ulu Pandan WS, 1 Business Park Drive, Singapore 6		
	Repairer	SBS TRANSIT LTD (HQ)		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	