

### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL INV No. AC2105435

64 CECIL STREET INV Date 02/08/2021

#05-02 IOB BUILDING Reference CS3/GRB21007956/Etf3e2

SINGAPORE 049711 Code GRB

### PROFESSIONAL SERVICE FEE

Vehicle No. SLK 6312K Bill cancel refer to new invoice No. AC2200569 27/01/2022 \$261.00

Insured Veh. SLL 8219D

Claim No. MFL2021D0003212

Policy No. D21MFL0000447

Accident Date 26/07/2021

Inspection Date 27/07/2021

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 27.07.2021 01.00pm	
- Dismantle Inspection 28.07.2021 02.30pm	
- After Repair Inspection 30.07.2021 03.30pm	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

**KHM** 



# **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL INV No. AC2200569

64 CECIL STREET INV Date 27/01/2022

#05-02 IOB BUILDING Reference CS3/GRB21007956/Etf3e2-1

SINGAPORE 049711 Code GRB

### PROFESSIONAL SERVICE FEE

Vehicle No. SLK 6312K

Insured Veh. SLL 8219D

Claim No. MFL2021D0003212

Policy No. D21MFL0000447

Accident Date 26/07/2021

Inspection Date 27/07/2021

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Merimen Fee	11.00
**Note: Pls discard Inv.AC2105435 dated 02/08/2021 \$140.17**	
Subtotal	261.00
GST (7%)	18.27
Grand Total	279.27

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 

**KHM**