

⏪	<	1 of 2 ?	>	⏩	↺	↻	100% ▼	🖨	📄	Find Next
---	---	----------	---	---	---	---	--------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/GRB21007956/Etf3-1 Date: 14/01/2022 Code: GRB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLL 8219D	Veh. Inspected	SLK 6312K	
Policy No.	D21MFL0000447	Coverage (\$)	0.00	
Claim No.	MFL2021D0003212	Excess (\$)	0.00	
Assign From	CARINE KEK PHER SER	Assign Date	14/01/2022	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	26/07/2021	Inspection Date	14/01/2022	
Survey held at	FIX AUTO PTE LTD 5 SOON LEE STREET, #01-61, PIONEER POINT, SINGAPORE 627607			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				