

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Supplementary estimate

Vehicle number: XE2632C

Make & Model: Mitsubishi Fuso

No.	Description of spare parts	Qty	List price	Amount
1	Aircon condenser	1		\$ 2,023.00
			Total	\$ 2,023.00
			Less 10%	\$ 202.30
			Total	\$ 1,820.70

X BT (Old Damaged)

	Labour and painting			Amount
1	Labour charges to remove and reinstall aircon condenser and pipes to assist repair. To refill aircon gas			\$ 400.00

X

Total Amount**\$ 2,220.70**