



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22000558/Vqy3m4	
			Date: 02/09/2022	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHB 281A	Veh. Inspected	SJK 2805E	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/12/21/2082	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	14/01/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA WISH 1.8	c.c	1794	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JTDER12W003000825	Colour	GREY	
Odometer	162596 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	BRIDGESTONE	5 mm	
L/H Front Tyre	205/55 R16	BRIDGESTONE	5 mm	
R/H Rear Tyre	205/55 R16	BRIDGESTONE	5 mm	
L/H Rear Tyre	205/55 R16	BRIDGESTONE	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	31/12/2021	Inspection Date	17/01/2022	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	