

Ricardo Auto Centre Pte Ltd (Co.Reg.No:198102182M)

160 Sin Ming Drive, #02-02, Sin Ming AutoCity

Singapore 575722

Tel: 64752112 Fax: 64754666 Email: grace@ricardo.com.sg

(SUPPLEMENTARY)INSURER: **ECICS Limited (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC21A00043604	Date of Loss:	12/01/2022
Vehicle Reg. No.:	SFR8000G	Driveable?	YES
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	DU NINI	Contact No:	+6593824932
Make/Model:	TOYOTA HARRIER 2.0, 2.0 PREMIUM AT AIRBAG 2WD (A)	Vehicle Reg. Date:	12/05/2017
Vehicle Colour:	MAROON	Chassis No:	ZSU600106307
Engine No:	3ZRC004933		
Odometer:	28464 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	9		
Description of Accident/Loss	REFER TO GIA REPORT		
Present Location:	RICARDO AUTO CENTRE PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	132.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	132.00
+ GST 7.00% (S\$)	9.24
Nett Amount (S\$)	141.24
+ Previous Estimates (S\$)	12,328.75
Claim Total (S\$)	12,469.99

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 28 Jan 2022)

Parts: N/A TOYOTA HARRIER 2.0 2.0 PREMIUM AT AIRBAG 2WD (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ricardo Auto Centre Pte Ltd/SFR8000G/28/01/2022 16:13

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Supply & replace rear bumper sensor (including painting to body colour)	0.00	0.00	*120.00	F ✓
						Sub Total (\$\$)	120.00
						+ Margin on L,N Items 10.00% (\$\$)	12.00
						Total Parts (\$\$)	132.00

Ricardo Auto Centre Pte Ltd/SFR8000G/28/01/2022 16:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Ricardo Auto Centre Pte Ltd/SFR8000G/28/01/2022 16:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >