

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

riog. No. 10000710011 Co. 10000710011					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref	: CS/AGI22000569/Vtf3n2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Dat	e: 28/02/2022	
			Cod	de: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJQ 3913M	Veh. Inspected	FBP 1064B	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10013351/KY	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	17/01/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA AEROX	c.c	155	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	MH3SG4640JJ046536	Colour	BLACK	
	Odometer	19833 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	110/80 R14	PIRELLI	6 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	110/80 R14	PIRELLI	6 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S,N/S BODY AND FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	11/01/2022	Inspection Date	20/01/2022	
	Survey held at	Survey held at ERZAT LEE MOTOR TRADING PTE LTD 25 KAKI BUKIT ROAD 4, #03-37, SYNERGY @ KB, SINGAPORE 417800			
5a.					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: