



HUA HONG PRIVATE LIMITED

10 Kaki Bukit Avenue 4 #04-63 Premier@Kaki Bukit Singapore 415874
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

19 January 2022

QUOT202201-000004

HHTPCLAIMS22-05

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 ANSON RD, #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Xiao Chen

Attn: Motor Claims Department

ACCIDENT INVOLVING SMH8547R & GBK3616Y ON 13/01/2022 ALONG BUANGKOK DRIVE AT ABOUT 1512 HOURS

Insured : HUA HONG PTE LTD
Vehicle Registration No. : SMH8547R
Vehicle Make : HONDA
Vehicle Model : SHUTTLE HYBRID 1.5 AUTO
Vehicle Chassis No. : GP72004617
Policy No. : 5109921641-02
Date of Accident : 13/01/2022

Type of Claim:

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Front Bumper <i>Distorted</i>		\$ 2,101.00 <i>1050.</i>
2	10	Front Bumper Clips <i>New</i>	\$ 5.00	\$ 50.00 <i>30</i>
3	2	Front Bumper Side Retainer (LH/RH) <i>RH Dented</i>	\$ 44.10	\$ 88.20 <i>44.10</i>
4	1	Front Bumper Towing Cover <i>missing</i>		\$ 57.00
5	1	Front Bumper Reinforcement <i>Dented.</i>		\$ 594.00 <i>420</i>
6	1	Front Bumper Undercover <i>torn</i>		\$ 600.60 <i>220</i>
7	1	Front Bumper Garnish (RH) <i>New</i>		\$ 87.00 <i>x</i>
8	1	Front Fender (RH) <i>Dented.</i>		\$ 1,035.20 <i>452</i>
9	1	Front Fender Innershield (RH) <i>Torn</i>		\$ 241.00 <i>168</i>
10	10	Front Fender Innershield Clips <i>New</i>	\$ 5.00	\$ 50.00 <i>30.</i>
11	1	Front Fender Logo (Hybrid) <i>New</i>		\$ 131.80 <i>65</i>
12	1	Front Fender Quarter Glass (RH) <i>lt</i>		\$ 581.40 <i>✓.</i>
13	1	Front Door (RH) <i>Reps</i>		\$ 1,697.40 <i>x.</i>
14	1	Front Door Sticker (RH) <i>New</i>		\$ 135.00 <i>60.</i>
15	1	Front Door Window Outer Moulding (RH) <i>lt New</i>		\$ 226.80 <i>x.</i>
16	1	Front Door Side Mirror Assy (RH) <i>Dented</i>		\$ 1,147.40 <i>685</i>
17	1	Front Door Side Mirror Cover (RH) <i>crushed</i>		\$ 165.00 <i>85</i>
18	1	Front Headlamp (RH) <i>crushed.</i>		\$ 3,473.40 <i>2250</i>
19	1	Front Headlamp Bracket (RH) <i>crushed</i>		\$ 121.50 <i>45.</i>
20	1	Front Grille Base		\$ 790.00 <i>x</i>
21	1	Front Grille Outer Chrome Top		\$ 725.00 <i>x</i>
22	1	Front Grille Outer Chrome Bottom		\$ 441.40 <i>x</i>
23	1	Front Grille Emblem		\$ 82.20 <i>x.</i>
24	1	Washer Tank <i>Rehnd</i>		\$ 256.40 <i>125</i>

6332.50

5066

CONTINUE NEXT PAGE



HUA HONG PRIVATE LIMITED

10 Kaki Bukit Avenue 4 #04-63 Premier@Kaki Bukit Singapore 415874
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

19 January 2022

QUOT202201-000004
HHTPCLAIMS22-05

ACCIDENT INVOLVING SMH8547R & GBK3616Y ON 13/01/2022 ALONG BUANGKOK DRIVE AT ABOUT 1512 HOURS

Estimate Repair List for vehicle SMH8547R - HONDA SHUTTLE HYBRID 1.5 AUTO

S/N	Quantity	Description	Unit Price S\$	Amount S\$
				\$ 14,878.70
			Less 20%	\$ 2,975.74
				\$ 11,902.96
25	1	Sealant <i>ME ME</i>	NETT	\$ 40.00 <i>T</i>
26	1	Front Rim (RH) <i>cut</i>	NETT	\$ 350.00 <i>✓</i>
		To dismantle and change front bumper, front fender (RH), front reinforcement, front door (RH), front side mirror (RH), front headlamp (RH). Knocking front fender inner panel (RH)		\$ 1,200.00 <i>8w.</i>
		To perform wire checking		\$ 50.00 <i>30</i>
		To dismantle & replace front door (RH) mechanism and fitting to new door		\$ 80.00 <i>✓</i>
		To remove & replace new front door quarter glass (RH)		\$ 120.00 <i>60</i>
		To spray front bumper, front fender (RH), front reinforcement, front door (RH), front fender inner panel (RH), front side mirror cover (RH)		\$ 1,400.00 <i>1000</i>
				\$ 15,142.96
			7% GST	\$ 1,060.01
			Total	\$ 16,202.97

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Admin Lj
F/S 06 Days.

total: 7386
F/S: 5-9K

Authorised by Claims Dept