



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC22000586/Evf3e2	
			Date: 19/05/2022	
			Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SKD 9450Z
	Policy No.	Z21VP05028701	Coverage (\$)	0.00
	Claim No.	21/22/22/VP05/025375	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	17/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 630i	c.c	2996
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	WBAEB12050B698044	Colour	GREY
	Odometer	141976 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	275/35 R19	MICHELIN	5 mm
	L/H Front Tyre	275/35 R19	MICHELIN	5 mm
	R/H Rear Tyre	275/35 R19	MICHELIN	5 mm
	L/H Rear Tyre	275/35 R19	MICHELIN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/01/2022	Inspection Date	26/01/2022
	Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks				
	A) THE MARKET VALUE IS S\$87,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	